



Notes:					
FOR VEHICLES WITH KEYLESS RIDE (CODE: X193A)					
#	Part Number	Description	lb	Qty	Each
01	66 12 8 559 944	KEYLESS RIDE CONTROL UNIT	965.73	1	\$835.33
Coded part. Dealer install only. Please see your local dealer for this part.					
02	07 11 9 904 919	WASHER - 8-200-ZNFE SW		2	\$3.00
					
03	51 25 7 711 811	LOCK SCREW - M8X31-MK-ZNS3	0.03	2	\$5.26
 <p>This lock screw (1st image) must be drilled out to be removed. This bolt requires BMW Special Tool #51 0 531 (2nd image) to be installed. Found in the maingroup for tools. The tool will fit any 1/4" drive. If you would like a substitution for the lock screw, Order by Part Number 07119904102 (3rd image). Be sure to use blue Loctite as the substitution does not come with it factory applied.</p>					
04	66 12 8 549 911	EMERGENCY CODE	35.27	1	\$80.36
ATTENTION! IT IS MANDATORY THAT KEY FOB TRANSMITTERS MUST BE TAUGHT-IN TO THE VEHICLE. TO DO SO, PLEASE OBSERVE THE REPAIR INSTRUCTIONS. :					
05	66 12 8 555 168	KEY FOB TRANSMITTER KEYLESS RIDE - 434 MHZ	95.48	1	NA
Needs to be coded/programmed by your dealer.					
Not available for over the counter or mail order sales.					
06	66 12 8 531 633	ANTENNA	0.12	1	\$98.57
08	66 12 6 912 985	BATTERY - 3,2 V - CHROME2032	6.55	X	\$6.11
